DELHI JAL BOARD: GOVT. OF NCT OF DELHI OFFICE OF THE EXECUTIVE ENGINEER (RWH/GWC) ROOM NO. 209, VARUNALAYA PHASE-I KAROL BAGH, NEW DELHI - 110005 # 23558264

No./DJB/EE(RWH/GWC)/2019/ 994 To,

DATED: 13/03/19

Principal, Shri Hazari Lal Public School, Village & Post Khera Kalan, Delhi-110082

Subject:-Regarding adequacy of rain water harvesting system at Shri Hazari Lal Public School, Village & Post Khera Kalan, Delhi-110082.

Sir/Madam,

The above said unit has been inspected by Joint Inspection Team on dated 11.03.2019, constituted by Hon'ble NGT in O.A. No. 217/2016. It was found that one No. RWH pit with one No. old recharge well is existing at site.

The existing RWH structure is adequate to harvest the roof top run-off for catchment area of above said unit. The RWH structure was found to be functional at the time of inspection.

You are advised to keep the existing RWH system neat & clean & maintain the same periodically. Rain Water conveyance system shall be duly kept connected to RWH pits and filter media shall be maintained and kept neat & clean, as per DJB norms and over flow shall always remain connected to municipal drain.

Sh. Hazari Lal Public School Khera Kalan, Delhi-82

VARUNALAYA BHAWAN, JHANDEWALLAN, N.D.-05

Sh. Hazari Lal Public School Khera Kalan, Delhi